



GUARDIANDOORS.COM

0800 783 6602

ROLLER SHUTTERS - SECTIONAL OVERHEAD DOORS - INSULATED DOORS - FOLDING DOORS
STEEL DOORS - FIRE RATED DOORS - SECURITY DOORS - SLIDING GATES - HIGH SPEED DOORS

Ronald McDonald House Camberwell

6 Windsor Walk
Camberwell
London
SE5 8YY

By Email: keith@kor-web.com

Guardian Industrial Doors

45 Progress Road
Leigh-on-Sea
Essex
SS9 5PR

INVOICE

Job Number	Quote Number	Invoice Number	Invoice Date
R51747	E59188	64446	11/07/2023
Your Purchase Order	Your Work Order	Other Ref	Your Asset No.
PO3347	-	-	-
Site Address	Ronald Mcdonald House, 6-9 Windsor Walk, Camberwell SE5 8BB		

Description of Works	Value
4002-11964 - FIRE SHUTTER TUBE OP (Office) w3w: local.dairy.went	£522.00
Further to our recent service visit S51441 the following works are required to return your fire shutter to safe working order. The uninterrupted power supply (UPS) has failed and requires replacement. This UPS ensures the shutter can close in the event of power loss and a fire activation and is required to make the shutter compliant with product and fire regulations. To return to site and replace the unit and recommission the door, test adjust and leave in full working order.	
Total Job Value	£522.00
Balance Outstanding	£522.00
20% VAT	£104.40
TOTAL DUE	£626.40

BANK DETAILS - SORT CODE 16-31-50 ACCOUNT NUMBER 11578390
CHEQUES PAYABLE TO: GUARDIAN INDUSTRIAL DOORS LTD
TERMS NETT MONTHLY
UTR 36650 07741 VAT REG NO.328 5339 44
EORI Number: GB328533944000

CERTIFIED
ISO 9001



Guardian Industrial Doors Ltd
Managing Director: RW Everitt
Registered Office: 45 Progress Road, Leigh on Sea, Essex SS9 5PR
Registered in England No 1447746